

State of Kansas . . . John Carlin, Governor

# DEPARTMENT OF HEALTH AND ENVIRONMENT

Joseph F. Harkins, Secretary

Forbes Field  
Topeka, Kansas 66620  
913-862-9360



September 11, 1981

Mr. Wilbur W. Bradley, Plant Manager  
Olin Water Service  
3155 Fiberglass Road  
Kansas City, Kansas 66115

  
R00011103  
RCRA Records Center

Re: Resource Conservation and Recovery Act (RCRA) Compliance Schedule

Dear Mr. Bradley:

On April 22, 1981 a RCRA compliance inspection was held by the U.S. E.P.A. to evaluate the facility's compliance with the hazardous waste management regulations established pursuant to RCRA. The inspection identified the following items which need to be addressed:

- (1) A plan for carrying out routine inspections of the facility must be developed and implemented in accordance with Sections 265.15, and 265.174.
- (2) Containers holding ignitable or reactive waste must be located at least 50 feet from the facility's property line. Section 265.176.
- (3) The storage of drums containing hazardous waste must be in an orderly manner to provide sufficient aisle space to allow the unobstructed movement of personnel and fire protection equipment in the event of an emergency. Section 265.35.
- (4) A contingency plan must be developed and must include the items and meet the requirements set forth in Sections 265.51 - 265.54.

The preceding comments will assist you in complying with the regulations set forth by the Resource Conservation and Recovery Act. You should be able to complete the necessary actions by November 1, 1981. At this time we will contact you to observe your changes.

Sincerely yours,

DIVISION OF ENVIRONMENT

*Randy D. Bradley*  
Randy D. Bradley

Hazardous Waste Management Section  
Bureau of Environmental Sanitation

RDB:kaa

cc: EPA - Wayne Kaiser  
Northeast District  
Tom Gross

